

# AMPLIFIER ANTENNA ASSY REPLACEMENT

6715Y-01


HINT:

- COMPONENTS: See page 76-21
- Installation is in the reverse order of removal.

## 1. REMOVE ROOF HEADLINING ASSY (SEE PAGE 76-21 )


HINT:

Refer to the procedures up to "REMOVE ROOF HEAD LINING ASSY".



## 2. REMOVE ROOF SIDE RAIL BRACKET RH

- (a) Remove the 4 bolts and roof side rail bracket RH.



## 3. REMOVE AMPLIFIER ANTENNA ASSY

- (a) Disconnect the 2 connectors.  
(b) Remove the 3 clamps, bolt and amplifier antenna assy.

## 4. INSTALL ROOF HEADLINING ASSY (SEE PAGE 76-21 )

HINT:

Refer to the procedures from "INSTALL ROOF HEAD LINING ASSY".