

PROBLEM SYMPTOMS TABLE

Symptom	Suspected Area	See page
Sliding roof system operates abnormally.	1. Slide roof control switch	05-1981
	2. Sliding roof control motor and relay	05-1981
	3. Wire harness	-
Sliding roof system stops operation halfway. (No foreign materials are trapped in motor assembly)	1. Slide roof control switch	05-1981
	2. Sliding roof control motor and relay	05-1981
	3. Wire harness	-